



## **POPCORN** **OPERATING INSTRUCTIONS:**

1. Plug into a 15amp/120V designated electrical outlet. Place popcorn machine on cart or on a sturdy table with table cover protector.
2. Switch on the LIGHT and HEATER, let heat for 3 to 4 minutes. Empty the oil bar from the NakPack into the heater.
3. Once oil bar is heated/melted (30 sec - 1min), turn on the STIRRER switch and add popcorn kernels.
4. Do not exceed 1 pre-measured Nak-Pak.
5. Once popping has completed turn off the STIRRER and HEATER switches and carefully dump/tip all popcorn from the kettle with handle.
6. Reference the side of the popcorn machine door for additional information.

**CAUTION: Kettle will be HOT!**

### Important!

- Adult supervision & operation is required at all times
- Never put popcorn kernels in dry kettle – oil is required
- Turn kettle "OFF" when not in use
- Secure the popcorn machine when transporting, DO NOT TIP!

Need help?

Call Moonwalk Entertainment at 705-715-2925